



DANGER

Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.



CAUTION

If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.

LA OR MA

LA OR MA

- PLATE-COAX 13406-01-CHT
- LABEL-SAT 13425-01-CHT
- ADAPTER 82134-01-000 (2)
- NUT 82136-01-000 (2)
- SCREW 667-10-08U (2)

- (25F) DVD PLAYER 136764-02-000
- FASTENER-DUAL LOCK 85774-01-000
- 85774-02-000

- (72M) VCR_STEREO 124073-11-000
- FASTENER-DUAL LOCK 85774-01-000
- 85774-02-000


- (20C) (42Z) TV 25" STEREO 130121-06-000
- (21V) (42E) TV 27" STEREO 136162-01-000

- (20C) SPEAKER 124883-03-000
- GRILLE 124883-04-000
- SCREW 611-08-08B (4)

- (35P) CONTROL CENTER SWITCHING 86757-04-000
- FASTENER-DUAL LOCK 85774-01-000 (220) (2)
- 85774-02-000 (220) (2)

- SWITCH 89308-01-CHT
- PLATE-SWITCH 98351-16-CHT
- SCREW 611-06-10J (2)
- (SEE DETAIL EA)

- PLATE-WALL ANTENNA 86784-03-CHT (193)



DETAIL EA

- (21V) SOUND SYSTEM DELUXE
- (20C) SOUND SYS. DLX. W/O-SURROUND
- (42E) TV-27" COLOR, STEREO W/REMOTE
- (25F) DIGITAL VIDEO DISC PLAYER
- (78K) SATELLITE DISH-AUTOMATIC
- (72M) VCR-STEREO
- (42Z) TV-25" COLOR STEREO
- (35P) VIDEO SELECTION SYSTEM
- (193) TV ANTENNA

FOR DETAIL CALLOUTS SEE DWG NO. 130375-01-000

NOTES: ADVANTAGE UNITS ONLY.