



DANGER


Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.



CAUTION

If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.

RELEASE	REV/DATE	DWG NO	145021
REV ZONE	REVISION RECORD	DATE	DFTR-ORIG
B A7	ADDED RCP-FREEZER	04/09/03	2245-3904
C CB	GEN WIRES CHANGED TO 8 GAUGE	04/23/03	1612-4118
D A7	ADD DRESSER RECP	05/07/03	1612-4118
E AB	ADDED FEATURE 11E	06/03/03	4118-4118
F D4	REMOVE RIFRIGERATOR FROM INVERTER PANEL	09/09/03	1612-4118



- NOTES:
- 5 WIRE IN SIDEWALL
 - 4 WITHOUT 12F
 - 3 WIRE ROUTED IN ROOF.
 - 2 WIRE ROUTED IN SIDEWALL.
 - 1 ALL OUTLETS DOWN STREAM AND INCLUDING THIS OUTLET ARE GROUND GAULT INTERRUPT PROTECTED.

- 11E REFRIGERATOR/FREEZER PORTABLE
- 12F POWER CORD REEL
- 2IN DISHWASHER/BUILT-IN
- 265 CODES/STANDARDS - CSA/CMVSS
- 1B1 CODES/STANDARDS - USA

WINNEBAGO COPYRIGHT 2003 WINNEBAGO INDUSTRIES, INC.

DFTR	ORIG. DATE
CHKR	ALL DIMENSIONS ARE IN MILLIMETERS
P.E.	
M.E.	FIRST USED
DSNR	04 S40AD
UNSPECIFIED TOLERANCES ARE:	MATERIAL:
WHOLE DIM (X)	:
ONE-PLACE (X.X)	:
TWO-PLACE (X.XX)	:
ANGLE	:
THIRD ANGLE PROJECTION	

DO NOT SCALE DRAWING

TITLE: WIRING DIAGRAM-BODY, 110V

SHEET 1 OF 1 PART NO 145021

REF: 1 09/10/03