




DANGER

Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.



CAUTION

If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.



- NOTES:
- (3) WIRE IN FLOOR
 - (4) WIRE IN ROOF
 - (3) WIRE IN SIDEWALL
 - (2) WIRE BELOW FLOOR
 - (1) ALL RECEPTACLES DOWNSTREAM PROTECTED BY GFCI.

- (26U) COFFEE MAKER
- (26E) COFFEE MAKER-WITHOUT
- (25D) A/C ROOF AIR (1) 14,800 BTU
- (193) TV ANTENNA
- (144) REFRIGERATOR-DOUBLE DOOR
- (13A) MICROWAVE OVEN
- (1D5) ENTERTAINMENT CENTR/EXT W/CD
- (1B1) CODES/STANDARDS USA
- (76C) ENTERTAINMENT CTR/EXT CASSETTE
- (49X) BED-QUEEN - BACKWALL
- (45G) BED-TWINS
- (40T) GEN-5.0KW ONAN-GAS-EMERALD
- (39E) GEN-6.5KW ONAN-GAS-EMERALD
- (39E) GEN-4.0KW ONAN-GAS-EMERALD
- (26E) CODES/STANDARDS-CSA/CMVSS

(12D) (1B1) (26E)

WINNEBAGO O1 F31B

DATE	BY	REVISION

WIRING DIAGRAM-BODY 110V

NO. OF SHEETS: 1 OF 1
 SCALE: AS SHOWN
 ALL DIMENSIONS ARE IN MILLIMETERS

REF: 131920-A 1