




DANGER

Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.



CAUTION

If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.



- ④ WIRE ROUTED IN ROOF.
- ③ WIRE ROUTED IN SIDEWALL.
- ② ALL OUTLETS DOWN STREAM AND INCLUDING THIS OUTLET ARE GROUND FAULT INTERRUPT PROTECTED.
- ① LEAD SUPPLIED WITH CONVERTER.

- ①④④ REFRIGERATOR-DOUBLE DOOR
- ④⑤⑥ BED-TWINS
- ④⑩⑩ GEN-4, 0KW-ONAN-GAS-MICROLITE
- ③⑨⑨ EXT RECEPTACLE DPLX 120VAC
- ①⑨③ TV ANTENNA
- ①③④ MICROWAVE OVEN
- ①②⑤ ENTERTAINMENT CENTR/EXT W/CD
- ⑦⑥⑦ ENTERTAINMNT CTR/EXT CASSETTE
- ④④④ BED-QUEEN SIDEWALL
- ②⑥⑤ CODES/STANDARDS-CSA/CMVSS
- ②⑥⑥ COFFEE MAKER
- ②⑤① A/C ROOF AIR (1) 14,800 BTU
- ①②① ELECTRICAL SYSTEM 30 AMP
- ①②① CODES/STANDARDS USA

WINNEBAGO 01 F26P

OF IN	DATE	UNSPECIFIED TOLERANCES ARE:	MATERIAL
CHP	DATE	WHOLE DIM (1X)	
D/E	DATE	ONE-PLACE (1X, 2X)	
D/E	DATE	TWO-PLACE (1X, 2X)	
CDR	DATE	THRU WHOLE PRODUCTION	

WIRING DIAGRAM-BODY 110V
 REF: 132104-A 135047