




DANGER

Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.




CAUTION

If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.



- NOTES:
- △ 8 SEE WIRING DIAGRAM-BODY, 12V FOR ADDITIONAL INFORMATION.
 - △ 7 SEE MANUFACTURERS DIAGRAM.
 - △ 6 WIRE ROUTED BELOW FLOOR.
 - △ 5 ONLY WITH 1L1
 - △ 4 WIRE ROUTED THRU ROOF.
 - △ 3 WIRE ROUTED THRU SIDEWALL.
 - △ 2 WIRE ROUTED THRU FLOOR.
 - △ 1 ALL OUTLETS DOWN STREAM AND INCLUDING THIS OUTLET ARE GROUND FAULT CIRCUIT INTERRUPT PROTECTED.



- 193 TV ANTENNA-AMPLIFIED SYSTEM
- 39A EXT RECEPTACLE DPLX 120VAC
- 1L1 TV-27\"/>

| | | | |
|-------------------------------------|--------------------------------------|---|-----|
| WINNEBAGO | | COPYRIGHT 2006 WINNEBAGO INDUSTRIES, INC. | |
| DFTR | ORIG. DATE | | |
| CHKR | ALL DIMENSIONS ARE IN MILLIMETERS | | |
| P.E. | | | |
| M.E. | FIRST USED | 08 228P | |
| DSNR | | | |
| UNSPECIFIED TOLERANCES ARE: | | MATERIAL: | |
| WHOLE DIM (X) | : | | |
| ONE-PLACE (X.X) | : | | |
| TWO-PLACE (X.XX) | : | | |
| ANGLE | : | | |
| THIRD ANGLE PROJECTION | | | |
| DO NOT SCALE DRAWING | | | |
| TITLE: WIRING DIAGRAM-BODY, 110V | | | |
| SHEET 1 of 1 | PART NO | 163768 | REV |
| REF: | 1 5/24/2007 | | |